



EZSentinel
Drag Conveyor Kit
No speed sensor

HMC005

Everything you need for a Drag Conveyor

Included in this kit are all of the components required to install monitoring on a drag conveyor. Sensors are supplied for 4 bearings. All hardware, cable protection and mounting brackets are included.



T BEARING TEMPERATURE



FI FIELD INTERCONNECT





EZSentinel
Drag Conveyor Kit
No speed sensor

HMC005

What's included:

Everything you need to setup hazards monitoring on a single drag conveyor:

Quantity	Part no.	Description
4	mTS012-4	4" tube bearing temperature sensors
4	mTS012-KIT	Bearing temperature tee fitting
2	mTB006-6	Field Interconnect - 6 port
2	mTB006-MTGKIT	Field Interconnect mounting kit: 1 – mTBBRKT 90° mounting bracket 2 - #10-32 x 3/8" pan head Phillips SS screws 2 - 1/4"-20 x 1.5" Pan head Phillips SS screws 2 – 1/4"-20 Nylock SS nuts
4	mLTT-60	72" cut lengths of plastic liquid tight tubing
8	PS0509N	Liquid tight connector straight, with watertight seal